

# Page 1 of 7 TOUCH FASTENER CONFIGURATIONS Howard A. Kingsford et al. 10/607,001 05918-314001




FIG. 1




FIG. 2



### Page 2 of 7 TOUCH FASTENER CONFIGURATIONS Howard A. Kingsford et al. 10/607,001 05918-314001




FIG. 3A




FIG. 3B



### Page 3 of 7 TOUCH FASTENER CONFIGURATIONS Howard A. Kingsford et al. 10/607,001 05918-314001




FIG. 4A




FIG. 4B



# Page 4 of 7 TOUCH FASTENER CONFIGURATIONS Howard A. Kingsford et al. 10/607,001 05918-314001





FIG. 5





# Page 5 of 7 TOUCH FASTENER CONFIGURATIONS Howard A. Kingsford et al. 10/607,001 05918-314001




FIG. 7A (PRIOR ART)

FIG. 7B







FIG. 8




# Page 6 of 7 TOUCH FASTENER CONFIGURATIONS Howard A. Kingsford et al. 10/607,001 05918-314001













FIG. 9A

FIG. 11A






FIG. 10

FIG. 12



# Page 7 of 7 TOUCH FASTENER CONFIGURATIONS Howard A. Kingsford et al. 10/607,001 05918-314001




FIG. 13